

Monthly Construction Progress Report September 16, 2019

 Exterior moisture barrier continues and rigid insulation has begun Upper level seating modification is reviewed and approved for concrete correction Interior walls continue with tape and bed, texture and painting has started Auditorium walls continue to be framed and drywall started Concrete slab for 2nd level is formed and reinforcing installed; Rough-in in progress Fire sprinkler interior lines are complete and preparation with FA and testing Plumbing mains are near complete and being tested Final door frames are delivered and installation near complete Electrician is pulling wire and preparing the panels HVAC contractor installing ductwork and VAV boxes in all areas Base material is being installed for the new parking lot and east driveway 		Hondo High School Improvements – Phase II
 Sidewalks continue and preparation for curbs along the street and drive Decision from A/E and city that fire hydrant will be relocated (per plans) Additional work on the mock-up is prepared and ready for review Walk-thru for review of all auditorium systems to identify boxes still needed Underground electrical started for new light poles 	Fine Arts Facility	 Upper level seating modification is reviewed and approved for concrete correction Interior walls continue with tape and bed, texture and painting has started Auditorium walls continue to be framed and drywall started Concrete slab for 2nd level is formed and reinforcing installed; Rough-in in progress Fire sprinkler interior lines are complete and preparation with FA and testing Plumbing mains are near complete and being tested Final door frames are delivered and installation near complete Electrician is pulling wire and preparing the panels HVAC contractor installing ductwork and VAV boxes in all areas Base material is being installed for the new parking lot and east driveway Sidewalks continue and preparation for curbs along the street and drive Decision from A/E and city that fire hydrant will be relocated (per plans) Additional work on the mock-up is prepared and ready for review Walk-thru for review of all auditorium systems to identify boxes still needed

LOOKING AHEAD:

- Concrete sidewalks and new asphalt paving along Avenue H, and the new parking lot
- Concrete modification of the upper seating section and mezzanine
- Auditorium scaffolding for overhead work

Hondo High School Improvements – Phase III				
Track Facility & Concession/Restroom	 Concrete placement is complete for the east side drainage flume (to the property line) Asphalt on the track and field events is complete Bleacher and Press box are complete Concession stand is turned over to HISD for use; adjacent sidewalk is completed Hellas has mobilized to begin the track surfacing First layer of the track surfacing has begun on the east side 			
	Restroom building permit is pending additional requests from the city plan review			

LOOKING AHEAD:

- New restroom building permit, foundation and utilities
- Completion of track surfacing

Roofing Projects (Insurance Claim)				
Meyer Elementary & McDowell Middle School Remaining Metal Roofs	 Purchase orders to be issued by HISD in order for material to be ordered-still outstanding Contractor will preparing schedule based on material order/delivery 			

Hondo High School Improvements – Phase I Warranty					
Hondo High School-Gym	•	Trane meeting to review the units trending data and the scheduling for training and acceptance			
		so that a new 2 year parts and labor warrantee would commence			



Hondo ISD Board Update















Hondo ISD Board Update











