

Monthly Construction Progress Report December 16, 2019

Hondo High School Improvements – Phase II				
<u>Fine Arts Facility</u>	 Power poles have been relocated and permanent power is completed Metal panel installation is near completed Masonry is near completed-north, south and east façade are being cleaned and west is 90% Second floor MEP is ongoing and unit piping is near complete and ready for testing Interior walls continue with final paint in classroom areas Exterior doors are installed and interior doors are in progress Glass installation is complete on the storefront entry (glass doors openings are protected) Auditorium overhead work in progress with drywall clouds, light fixtures and tape/bed/paint Fire sprinkler heads are being placed in ceiling grid and auditorium clouds Plumbing fixture installation is near complete Interior brick in the lobby is completed and drywall overhead framing in progress HVAC contractor continues installation of interior duct and diffusers in the grid Exterior condenser unit is delivered and being prepared for connection to 2nd floor unit Electrician continues to finalize distribution panels and main switch gear Data cabling is being pulled back to IDF and rack installation has begun Chair lift platform and mechanics are installed, including automatic doors Fire alarm cabling is near complete and panels are installed Theater rigging in the auditorium has completed the first light bar 			

LOOKING AHEAD:

- Removal of the auditorium scaffolding and interior finishes begin
- Theater rigging continues for the stage area
- HVAC units set and start-up of AC

Hondo High School Improvements – Phase III				
Track Facility &	Hydro-mulch on the infield and temporary irrigation have provided vegetation coverage			
Concession/Restroom	Perimeter fencing is completed except along the south street (pending concrete)			
	Retaining wall along the street is completed			
	Sanitary sewer line has been installed with cleanouts and ready for city connection			
	Restroom building under slab rough-ins completed and concrete foundation placed			
	Additional sidewalk at the building is completed			
	Water line and electrical underground services have been installed and connected			
	Grading for the new drive is ongoing			

LOOKING AHEAD:

- New restroom metal building and finishes February completion
- Substantial completion of Track and Field
- Training with Athletic staff on Musco lighting

Roofing Projects (Insurance Claim)			
Meyer Elementary & McDowell Middle School Remaining Metal Roofs	 Roof shop drawings in progress Material price increase will be submitted to insurance adjuster 		

Hondo High School Improvements – Phase I Warranty					
Hondo High School-Gym	•	Trane has completed all requirements and warranty documents are submitted for approval			



Hondo ISD Board Update















Hondo ISD Board Update











